








List of unsafe products

No.	Children Products	Name of Seller	Online Platform	Safety Concerns
Baby carriers				
1	MINE 4 Position Baby Carrier 	Qoostore	Qoo10	<ul style="list-style-type: none"> Warning label detached from the baby carrier during testing. Fastener broke during the test, posing a fall hazard. Instructions and warnings provided were not in accordance to the requirements (e.g. content, format, language).
2	OEM Adapt 3 Position Baby Carrier 	Dreamworks Mart	Shopee	<ul style="list-style-type: none"> Instructions and warnings provided were not in accordance to the requirements (e.g. content, format, language).



3	Sorbebe Airo Robic Hip Seat Baby Carrier 	Agape Babies	Agape Babies	<ul style="list-style-type: none"> • Instructions and warnings provided were not in accordance to the requirements (e.g. content, format, language).
4	I-Angel Miracle Hip Seat Carrier 	Koreanbabymarket	Lazada	<ul style="list-style-type: none"> • Warning label detached from the baby carrier during testing. • Instructions and warnings provided were not in accordance to the requirements (e.g. content, format, language).
Cots				
5	SG Baby Shop (Model No: SX)	SG Baby Shop	Qoo10	<ul style="list-style-type: none"> • Edges around the product were not well-rounded and could pose a laceration hazard. • Internal dimensions of the product do not meet the minimum requirement; this could pose a falling hazard as children may climb over the cot. • The locking devices do not meet the minimum force required to be operated, posing a stability hazard should it be unlocked accidentally.


				<ul style="list-style-type: none"> • Small parts such as, fasteners of locking devices and foam from the mattress may be detached, posing a choking hazard. • Slats of the bed broke when subjected to a durability test. The sharp edges formed from the breakage could pose a laceration hazard. • The plastic packaging used for the product is not perforated or marked with warning statement. This could pose a suffocation hazard if played with by children. • Instructions provided were not in official language – English.
6	<p>Premium Baby Bed Set (Model No: Hope HP 810M)</p> 	JIJI Baby	Qoo10	<ul style="list-style-type: none"> • Edges around the product were not well-rounded and could pose a laceration hazard. • Internal dimensions of the product do not meet the minimum requirement, and could pose a falling hazard as children may climb over the product. • The locking devices do not meet the minimum force required to be operated, posing a stability hazard should it be unlocked accidentally. • Presence of small, detachable parts that could pose a choking hazard. • Slats of the bed broke when subjected to a durability test. The sharp edges formed from the breakage could pose a laceration hazard.

				<ul style="list-style-type: none"> • Instructions provided were not in official language – English.
7	Puku Izzy Foldable Baby Cot (Model No: P30112) 	Puku	Lazada	<ul style="list-style-type: none"> • Edges around the product were not well-rounded and could pose a laceration hazard. • Internal dimensions of the product do not meet the minimum requirement; this could pose a falling hazard as children may climb over the product. • Presence of gaps where loops or loose clothing parts may get caught, posing a strangulation hazard. • The locked castors do not meet the minimum required force to be operated, this could pose a stability hazard if product is moved unintentionally. • Bed base may be adjusted without a tool; this could pose a stability hazard if adjusted unintentionally. • Small bits of foam from the mattress may be detached and pose a choking hazard. • The gaps between the foldable side and cot base do not meet the requirements, this could pose a pinching hazard. • The side rail of the cot base broke when subjected to a durability test. The sharp edges formed from the breakage could pose a laceration hazard.

				<ul style="list-style-type: none"> • The gap between cot's slats do not meet the requirement of 45-65mm, posing an entrapment hazard. • Instructions provided were not in accordance to the requirements (e.g. content, format, language).
8	Milano – Oxford 4 in 1 Convertible Cot (Model No: BD302) 	Baby Kingdom	Qoo10	<ul style="list-style-type: none"> • Edges around the product were not well-rounded and could pose a laceration hazard. • Presence of holes that do not meet the requirements in dimension (diameter or depth). These could pose a finger entrapment hazard.  <ul style="list-style-type: none"> • Instructions provided were not in accordance to the requirements (e.g. content, format, language).

Strollers

9	Baby YOYA Baby Cabin Travel 	Best Deal Home	Qoo10	<ul style="list-style-type: none">• The restraint system and fasteners were not able to prevent the test mass from falling out during testing.• The tether strap was found to be too long and posed an entanglement hazard.• The product failed to meet stability requirements and overturned during testing.• The product broke when it was used over irregular test surfaces.• The product and its packaging do not have information provided in official language – English.
10	Belecoo Compact 	The Living Store	Qoo10	<ul style="list-style-type: none">• The tether strap was found to be too long and posed an entanglement hazard.• Foam from the bumper bar detached during testing and posed a choking and ingestion hazard.• The product failed to meet stability requirements and overturned during testing.• The product and its packaging do not have information provided in official language – English.

11	Seebaby Little Monster 	Cutebaby	Qoo10	<ul style="list-style-type: none"> • The restraint system and fasteners were not able to prevent the test mass from falling out during testing. • Pinching points were found in multiple areas of the product. • The parking device could not be simultaneously engaged with a single action on multiple wheels. To park the stroller, caregivers will need to go through a few steps. This poses a risk where caregivers may partially park the stroller instead causing it to continue moving • The product failed to meet stability requirements and overturned during testing. • The product broke when it was used over irregular test surfaces. • The product and its packaging do not have information provided in official language – English.
----	---	----------	-------	--