

## **Philips Recalls Digital Video Baby Monitor SCD620**

Philips Singapore has announced a voluntary recall for the Philips Avent Digital Video Baby Monitor (SCD620). The battery in the parent unit may overheat while plugged into the electrical outlet, posing a fire hazard. Affected units were produced between January 2016 and January 2020.



Please refer to this [website](#) for more information on the recall and instructions on how to identify if your Philips Avent Digital Video Baby Monitor is affected by this recall.

Consumers with affected units should stop using the baby monitor and unplug it from the power outlet, then contact Philips' customer care team at +65 68823999 for a replacement.