

21 Oct 2019

## Panasonic Rice Cooker Power Cord Replacement

Panasonic has announced a voluntary recall of power cords supplied with certain models of rice cookers which were manufactured between 2016 and 2018. The affected power cords do not comply with the safety standards prescribed by Enterprise Singapore.



Consumers are advised to stop using rice cookers with the affected power cords and contact Panasonic Singapore for a free power cord replacement.

For a list of affected rice cooker models and instructions on how to identify them, visit: [www.panasonic.com/content/dam/Panasonic/sg/en/dhp/spotlight/RC-Power-Cord-Replacement-Website-Notice-8-Oct.pdf](http://www.panasonic.com/content/dam/Panasonic/sg/en/dhp/spotlight/RC-Power-Cord-Replacement-Website-Notice-8-Oct.pdf).

Consumers may also contact Panasonic Singapore's customer service at +65 6222 7222 for more enquiries.