


Revlon RVST2029B

Date published: 7 March 2014

Product information

Name of product	Revlon RVST2029B
Product description	Blue-coloured hair straightener 
Identifying features/ Batch	2-pin plug that is not suitable for local use
Sample taken from	Koh Yeu Electrical Co.
Comments	<p>During the test on this sample, the hair straightener was found to be fitted with a 2-pin plug that does not meet the requirements of EN 50075. It is thus not suitable for local use. The product also does not meet various requirements of IEC 60335-2-23, including a supply cord that was found to be unsheathed.</p> <p>No reports of incidents or injuries related to the use of this product have been received to date.</p>

What should consumers do?

Consumers who have bought the product are advised to stop using it immediately.