

**Kenwood voluntarily replaces “Julienne” disc of food processor models FPM800 and FPM810**

Kenwood has announced a voluntary corrective action for the “Julienne” disc on its food processor models FPM800 and FPM810. Parts of the “Julienne” disc can potentially detach during use, creating a potential ingestion risk.



The affected “Julienne” discs for the FPM800 and FPM810 food processors were manufactured between January 2019 and December 2021. Affected consumers will be able to get a replacement “Julienne” disc free of charge.

Consumers are advised to check if their “Julienne” disc is affected by visiting the supplier’s website at [https://shop.kenwoodworld.com/kw\\_sg/kw\\_sg\\_product\\_servicing\\_repairs](https://shop.kenwoodworld.com/kw_sg/kw_sg_product_servicing_repairs).

